

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

and the desired the second
ng the Inspection:
vironmental Scientist
vironmental Scientist III
V

Inspection Report

Permit Number:	C0150009
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, August 12, 2008
Start Date/Time:	8/12/2008 12:55:00 PM
End Date/Time:	8/12/2008 3:40:00 PM
Last Inspection:	Friday, May 09, 2008

Inspector: Pete Hess, Environmental Scientist III

Weather: <u>Sunny; cooler, 80's F.</u> InspectionID Report Number: <u>1729</u>

Types of Operations

Accepted by: jhelfric 8/18/2008

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: TRAIL MOUNTAIN MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

3,539.00	Total Permitted		
10.69	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Current Acreages

Mineral Ownership

✓ Federal
✓ Underground

✓ State
□ Surface

□ County
□ Loadout

✓ Fee
□ Processing

□ Other
□ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The site remains in temporary cessation status; there is no activity at the surface facilities area. The site has received rain recently.

Inspector's Signature:

Liter Dess

Date

Wednesday, August 13, 2008

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150009 Inspection Type: COMPLETE

Inspection Date: Tuesday, August 12, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark			
2.	Signs and Markers	✓			
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	V			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	~			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation		✓		
14.	Subsidence Control	V		✓	
15.	Cessation of Operations		✓	✓	
16.8	a Roads: Construction, Maintenance, Surfacing	✓		✓	
16.Ł	Roads: Drainage Controls	V			
17.	Other Transportation Facilities	~			
18.	Support Facilities, Utility Installations	~			
19.	AVS Check	✓			
20.	Air Quality Permit	✓			
21.	Bonding and Insurance	✓		~	
22.	Other	✓		✓	

Permit Number: C0150009
Inspection Type: COMPLETE

Inspection Date: Tuesday, August 12, 2008

Page 3 of 3

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The Permittee's qualified personnel conducted the second quarter of 2008 impoundment inspection for the Mine site sediment pond on June 3, 2008. There were no structural weaknesses or unstable conditions observed by Mr. John Christensen, P.E., or Mr. Rick Cullum, registered land surveyor. The pond had 0.122 acre feet of sediment storage capacity remaining, as verified on June 3, 2008. Mr. Christensen certified the June 3 inspection report on August 12, 2008. The water level in the sediment pond appeared to be at least three feet below the primary spillway discharge elevation.

4.d Hydrologic Balance: Water Monitoring

The first quarter of 2008 surface and ground water monitoring data for the Trail Mountain permit area has been uploaded into the DOGM permanent data base. The Permittee continues to meet this Special Condition of the current State permit.

10. Slides and Other Damage

The shot crete failure behind the mine fan motor room remains unchanged.

14. Subsidence Control

Secondary extraction was discontinued at this site in May of 2001.

15. Cessation of Operations

There has been no change in the status of this site.

16.a Roads: Construction, Maintenance, Surfacing

The Permittee has recently graded roads inside the disturbed area perimeter which had rock debris from adjacent cut banks. Areas where erosion gullies had formed have been filled.

21. Bonding and Insurance

The Permittee's current general liability insurance coverage remains in effect until August 28, 2008.

22. Other

The chain link fence barricades at the portal entrances remain intact.